

General Environmental Incident Summary

Incident: 5832

Notice: 8/28/2018 1435

Occurred: 8/28/2018 1115

DEM Incident No:

No Further Action: ☒

Responsible Party: Nitro Green

County: Burleigh

Twp Rng Sec Qtr: 139 80 36

Lat Long + Method: 46.81176 -100.73080 Interpolation from map

Location Description: 100 yards north of intersection of E Rosser Ave and Bis Expwy

Submitted By Info: Justin Bashus
office manager
1500 E Main Ave
P O Box 1951
Bismarck ND 58501

Received By Info:

Contact Info: Justin Bashus
1500 E Main Ave
P O Box 1951
Bismarck ND 58501

Affected Medium: 04 - water and soil

Near. Occupied Bldg: 500 Feet

Type of Incident: Vehicle Accident

Release Contained: Yes

Reported to NRC: Unknown

Contaminant: nitrogen fertilizer and Vessel herbicide

Volume of Release: 50 gallons

Duration of Release: 30 minutes

Agriculture Related: No

EPA Extremely

Hazardous Substance: No

Number of Fatalities: 0

Number of Injuries: 0

Cause of Incident:

vehicle accident caused truck to tip over

Risk Evaluation:

none

Potential Env. Impacts:

some spill did make it to storm drain

Action Taken/Planned:

spill was contained with floor dry

Wastes Disposal Location:

contained in a rubber tote for the time being

Other Agencies Involved:

Local Fire Department, Local Law Enforcement

Updates

Date: 8/28/2018 ***Status:*** Reviewed - No Action Required

Author: Martin, Russell

Notes:

NDDoH inspector Duane Sandvick visited the incident site and talked with City of Bismarck employee onsite, and later followed-up with the fire department, and responsible party. City of Bismarck will be evaluating the storm drain, NDDoH inspector and City of Bismarck employee did not see any product leaving the outlet of the drain at the time of the site visit. No further follow-up required at this time.

Updated Volume: None at the time of this update